REET

#### **CERTIFICATE OF APPROPRIATENESS**

**Application Date:** January 8<sup>th</sup>, 2024

Applicant:, Manuel F. Zabala, owner

Property: Lot 8, Block 416. Baker W R NSBB Subdivision. The property includes a

two-story wood frame, 1,703 sq. ft. single-family residence situated on a 4,800 sq. ft.

interior lot.

**Significance:** Contributing Bungalow style residence, circa 1925.

Proposal: Alteration – Windows - Work Already Done - Certificate of Remediation (COR)

• Replace two (2) West elevations windows, due to storm damage.

Add 2" x 4" or similar sill to double window, to be compatible with North

elevation (Front) see attached photos.

Preserve frame and dimensions of the windows

**Public Comment:** No public comment received.

Civic Association: No civic association comment received.

ALL NEW WINDOWS MUST BE INSET 1¾ Inches – See Attachment Windows Must Be Equally Horizontally Divided 1-over-1

**Recommendation:** Denial - does not satisfy criteria, of Certificate of Appropriateness (COA) and Issuance of

Certificate of Remediation (COR) for windows installed with **Conditions**:

• Inset existing windows so that upper sash is inset at least 1¾ inches from Exterior Casing of Window Unit, see Attached Window Diagram.

 Add 2" x 4" or similar, windowsill to double window, to be compatible with North elevation windowsill (Front).

HAHC Action: -

Note: All materials in exterior walls, including windows, siding, framing lumber, and interior shiplap (if originally present) must be retained except where removal or replacement has been explicitly approved per this Certificate. Shiplap is an integral structural component of the exterior wall assembly in balloon framed structures and removal can cause torquing, twisting and collapse of exterior walls. Shiplap may be carefully shored and removed in small portions to insulate, run wire or plumbing, and should be replaced when the work is complete. Maintenance and minor in-kind repairs of exterior materials may be undertaken without HAHC approval, but if extensive damage of any exterior wall element is encountered during construction, contact staff before removing or replacing the materials. A revised COA may be required.

# **CERTIFICATE OF APPROPRIATENESS**



COA valid for two years from effective date. COA is in addition to any other permits or approvals required by municipal, state and federal law. Permit plans must be stamped by Planning & Development Department for COA compliance prior to submitting for building or sign permits. Any revisions to the approved project scope may require a new COA.

**ITEM A5** 2007 Kane Street Old Sixth Ward

#### **APPROVAL CRITERIA**

#### ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS


Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA - not applicable
$\boxtimes$			(1)	The proposed activity must retain and preserve the historical character of the property;
			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment;
			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
$\boxtimes$			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale;
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements;
			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.
				OLD SIXTH WARD DESIGN GUIDELINES
				In accordance with Sec. 33-276, the proposed activity must comply with the City Council approved Design Guidelines.

January 16, 2025 HPO File No. HP2024\_0307

REET

## **PROPERTY LOCATION**



#### **Building Classification**

Contributing

Non-Contributing

Park

REE"

# **PAST PHOTO - April 2010**



REE.

### **CURRENT PHOTO**



HPO File No. HP2024\_0307

REET


### **EXISTING CONDITION - WEST ELEVATION**



West Elevation - Vinyl Windows

REE.

#### **RED TAG VIOLATION**



PEFT

# **GOOGLE STREETVIEW (MAY 2022)**



Fixed Windows highlighted in red were replaced




Condition of COR: Add Windowsill to West Elevation Double Windows to resemble North Elevation Window, marked in Yellow.

REET

# Existing North Elevation

### **INTERIOR OF WINDOWS**






**Before** 

After





Windows must be 1-over-1 (equally horizontally divided)

134 inch minimum inset for Fixed Window

#### For more information contact:

**Houston Office of Preservation** 832-393-6556 historicpreservation@houstontx.gov

City of Houston | Planning and Development | Houston Office of Preservation