

U.S. Department of Housing and Urban Development 451 Seventh Street, SW Washington, DC 20410 www.hud.gov

espanol.hud.gov

Site-Specific Checklist

Project Information

Project Name: Home Repair Program

Responsible Entity: City of Houston, Housing & Community Development Dept.

Grant Recipient (if different than Responsible Entity):

State/Local Identifier: Texas/Houston

Preparer: David Alfaro, Environmental Investigator IV

Reviewer Name and Title: Melissa Lahey, Environmental Manager

Grant Recipient (if different than Responsible Entity):

Consultant (if applicable):

Direct Comments to: https://www.houstontx.gov

Project Location: 1270 Hopper Rd, Houston, TX 77037

Description of the Proposed Project [24 CFR 50.12 & 58.32; 40 CFR 1508.25]**:** The work on this house is part of the Home Repair Program – and entails Reconstruction.

A Tier I Broad Environmental Assessment was completed for the Single-Family Home Repair Program - CDBG for rehabilitation and reconstruction activities. The Authority to Use Grant Funds was approved on January 8, 2020. Please note supplemental reviews have been completed for this AUGF for additional grant years as funding has become available.

The goal in the HRP is to address repairs to alleviate threats to health, life, and safety hazards resulting from substandard conditions. We target homes owned and occupied by households earning no more than 80 % of Area Median Family Income.

Our program is not limited to low- and moderate-income elderly (62 or older) and disabled homeowners, but to also give priority to homes of employed applicants with minors, and unemployed applicants providing full-time care to disabled household members.

1. Tier III - Reconstruction

a) Those costing excess of \$80,000


Compliance with 24 CFR 50.4, 58.5, and 58.6 Laws and Authorities

Record below the compliance or conformance determinations for each statute, executive order, or regulation. Provide credible, traceable, and supportive source documentation for each authority. Where applicable, complete the necessary reviews or consultations and obtain or note applicable permits of approvals. Clearly note citations, dates/names/titles of contacts, and page references. Attach additional documentation as appropriate.

Compliance Factors: Statutes, Executive Orders, and Regulations listed at 24 CFR §58.5 and §58.6	Are formal compliance steps or mitigation required?	Compliance determinations			
STATUTES, EXECUTIVE OI & 58.6	RDERS, AND R	REGULATIONS LISTED AT 24 CFR 50.4			
Airport Hazards 24 CFR Part 51 Subpart D	Yes No	This location is outside of the HUD required search distances for civilian airports (2,500 feet) and military airports (15,000 feet). This project will be performed in zip code 77037, outside the zip codes in the airport clear zones.			
		As far as airports are concerned, the affected areas include zip codes 77017, 77032, 77034, 77059, 77061, 77062, 77073, 77075, 77338, 77396, and 77598.			
Flood Insurance Flood Disaster Protection Act of 1973 and National Flood	Yes No	The subject site is located inside of the 100- year floodplain; flood insurance is required by HUD federal regulations.			
Insurance Reform Act of 1994 [42 USC 4001-4128 and 42 USC 5154a]		1270 Hopper Rd. appears to be Zone AE- shaded, FEMA Flood Panel No. 48201C0490L, effective date 6/18/2007.			
		There is no evidence of preliminary or pending flood hazard changes for the property. See attached Flood Map Changes Viewer.			
STATUTES, EXECUTIVE OI & 58.5	STATUTES, EXECUTIVE ORDERS, AND REGULATIONS LISTED AT 24 CFR 50.4 & 58.5				
Coastal Zone Management Coastal Zone Management Act, sections 307(c) & (d)	Yes No	While parts of Harris County do lie within the boundaries of the Coastal Zone, the subject property is not within those boundaries. Please refer to attached map Figure 1.			

Contamination and Toxic Yes No Substances During a site visit to the subject property on 5/7/2024, no evidence of prior use as a gas station, dry cleaner, motor vehicle repair facility, printing facility, photo lab, junkyard or waste treatment, storage, or disposal facility such as sign posts, abandoned or apparent industrial drums on the site or adjoining properties. There is no evidence to suggest fill dirt has been brought onto the site from another location. No pits, ponds, lagoons, stained soil, or discolored water was observed. There was no discolored water was observed on the site or adjoining properties. There was no disclosed water was losserved on the site or adjoining site other than the one connected to the city water meter which does not apparent to pose any environmental risk of note. No chemical odors were detected during the site visit. A copy of the site-specific field contamination and ecological checkits is included. The water is supplied by a municipal water purveyor. The area is mixed-use properties, nerver on visible contor with normal conditions, it has no apparent visible signs of on-site or off-site contamination, and no unusual odors were noted. The drainage running along the front of the property was free and clear. The surrounding properties were single family homes or commercial facilities with no signs of industrial activity. The subject property is clear of environmental concerns.
on or adjacent to the subject property. The

Superfund equivalent site:
There is one (1) Superfund equivalent site. There is one (1) Superfund equivalent site within a mile radius of the subject property. Waste Oil Tank Services, 0.97 miles away, to the east. The site is over 1760 ft (1/3 mile) from the site, which per ASTM 2600-10 is outside the area of concern (AOC) for VOCs. Also, per TCEQ, No further Superfund environmental response actions are required on this former waste oil collection and transfer facility.
Leaking Petroleum Storage Tanks (LPSTs): There are four (4) LPST sites within a ½ mile radius of the subject property. All sites are over 528 ft (1/10 mile) from the site, which per ASTM 2600-10 is outside the area of concern (AOC) for Petroleum Hydrocarbon Contaminants of Concern (COCs).
Brownfield Site: There is one (1) brownfield site within a ¹ / ₂ mile radius of the subject property. 0.19 miles away to the southeast. The site is listed under the TCEQ Industrial and Hazardous Waste (IHW) Corrective Action Program. The Status is inactive, and the project phase is "completed workload". Per TCEQ, there are no Commissioners' Actions, Criminal Convictions, Complaints, Discharges, Emergency Response Events, Emission Events or investigations related with this property.
Based on the status and distance, these facilities are not expected to have an adverse impact on the subject property.
A copy of the NETROnline environmental radius report is included along with a radius map showing the relative location of the subject property to the abovementioned facilities.



		No environmental issues are foreseen, but in the event that any unexpected environmental conditions are discovered after closing/in the course of development, any ongoing work will need to cease until successful cleanup/mitigation of the unexpected environmental condition takes place, after which work can resume. HCDD environmental must be notified as soon as any such discovery is made so that the project can be re-evaluated.
Floodplain Management Executive Order 11988, particularly section 2(a); 24 CFR Part 55	Yes No	The subject site is located within the 100-year floodplain. Floodplain management regulations are applicable. See attached flood map. Elevation of residence will be required, and elevation certificate must be kept on file. 1270 Hopper Rd. appears to be Zone AE- shaded, FEMA Flood Panel No. 48201C0490L, effective date 6/18/2007.
Historic Preservation National Historic Preservation Act of 1966, particularly sections 106 and 110; 36 CFR Part 800	Yes No	The Texas Historical Commission has determined the project on the designated site complies with Section 106 of the National Historic Preservation Act of 1966. Property/properties are not eligible for listing in the National Register of Historic Places. Please see attached letter.
Noise Abatement and Control Noise Control Act of 1972, as amended by the Quiet Communities Act of 1978; 24 CFR Part 51 Subpart B	Yes No	See attached noise evaluation. 1270 Hopper Rd. is located less than 1,000 feet from a major thoroughfare, and less than 3,000 feet from a rail line. While the nearest airport (Bush) is less than 15 miles from the site and has been considered, its noise levels are below the elevated (i.e. 60 decibels (dB)) noise levels shown in the noise contour maps. Streets were determined to be major thoroughfares based on the Consolidated Transportation Planning Maps from the City of Houston's Planning & Development Dept. Noise levels at 1270 Hopper Rd. have been calculated at 68 dB which falls into HUD'S NORMALLY UNACCEPTABLE range.

Π		
		Noise mitigation will be required during
		construction. For Normally Unacceptable
		Noise Zone (NUNZ) projects: Mitigation
		measures to ensure interior noise levels under
		45 dB as confirmed by an architect or
		acoustical engineer will be required, with
		exterior noise levels for noise sensitive areas
		(i.e. areas where people congregate/relax like
		back yards, front porches, etc.) reduced to
		under 65 dB if feasible. These requirements
		will be a condition of receiving federal funds,
		and the project will be subject to HUD
		liability if these conditions are not met,
		penalties including but not limited to the
		payback of federal funds may be issued. The
		noise measurements performed by the architect/acoustical engineer shall include the
		use of HUD's Sound Transmission Classification Assessment Tool (STraCAT)
		web-based tool to determine noise levels and
		appropriate measures for mitigation. More
		information on the STraCAT tool can be
		found at:
		https://www.hudexchange.info/stracat/ (link
		to tool);
		https://www.hud.gov/sites/documents/ENV
		USERGUIDE STRACAT.PDF (user guide).
		Noise mitigation will be required during
		construction to reduce the internal noise level
		to 45 decibels. The noise mitigation will
		include, but is not limited to, STC rated
		material to comply with desired 45 decibel
		assembly. The contractor will furnish the
		certified documentation of sound attenuation
		rating for the record of this property. This
		amount of attenuation can be achieved
		presuming the use of insulating windows with
		STC-30 ratings, solid core doors with
		perimeter weather-stripping, attic insulation equivalent to R-13 or more and brick façade.
Wetlands Protection	X 7 X 7	· · · · · · · · · · · · · · · · · · ·
······································	Yes No	The project area does not lie within or near a
Executive Order 11990,		wetland, according to National Wetland
particularly sections 2 and 5		Inventory (NWI) maps.
ENVIRONMENTAL JUSTIC	E	

Environmental Justice Executive Order 12898	Yes No	While this site may potentially have the presence for asbestos, testing will take place, and abatement and proper disposal will be conducted as needed during demolition/reconstruction. Since all environmental issues are being addressed through mitigation as needed, issues regarding environmental justice are not foreseen.
--	--------	--

Field Inspection (Date and completed by): May 7, 2024, David Alfaro, Environmental Investigator

Mitigation Measures and Conditions [40 CFR 1505.2(c)]

Summarize below all mitigation measures adopted by the Responsible Entity to reduce, avoid, or eliminate adverse environmental impacts and to avoid non-compliance or non-conformance with the above-listed authorities and factors. These measures/conditions must be incorporated into project contracts, development agreements, and other relevant documents. The staff responsible for implementing and monitoring mitigation measures should be clearly identified in the mitigation plan.

Law, Authority, or Factor	Mitigation Measure
Flood Insurance	The subject site is located inside of the 100-year floodplain; flood insurance is required by HUD federal regulations.
	1270 Hopper Rd. appears to be Zone AE-shaded, FEMA Flood Panel No. 48201C0490L, effective date 6/18/2007.
Contamination and Toxic Substances	Due to the age of this property, testing for lead-based paint and asbestos will be required, along with any necessary abatement and/or disposal of these substances as required by all applicable state, local, and federal rules and regulations.
	Since the property under review does not contain a basement nor is a basement proposed during reconstruction, additional testing and mitigation are not required at this time. Should a basement area be constructed during this project, radon reduction best practices must be included during construction and the property should be tested for radon before becoming occupied. Any radon tests should be conducted in rooms that are living spaces, such as bedrooms, living rooms, or studies. If the test results are more than 4 pCi/L, a Soil Gas Mitigation Professional or a Qualified Contractor

Floodplain Management	 must be contacted to discuss the test results. If test results are consistently high enough, a mitigation system may be necessary. No environmental issues are foreseen, but in the event that any unexpected environmental conditions are discovered after closing/in the course of development, any ongoing work will need to cease until successful cleanup/mitigation of the unexpected environmental condition takes place, after which work can resume. HCDD environmental must be notified as soon as any such discovery is made so that the project can be re-evaluated. The subject site is located within the 100-year floodplain. Floodplain management regulations are applicable. See attached flood map. Elevation of residence will be required, and elevation certificate must be kept on file. 1270 Hopper Rd. appears to be Zone AE-shaded, FEMA Flood Panel No. 48201C0490L, effective date 6/18/2007.
Noise Abatement and Control	See attached noise evaluation. 1270 Hopper Rd. is located less than 1,000 feet from a major thoroughfare, and less than 3,000 feet from a rail line. While the nearest airport (Bush) is less than 15 miles from the site and has been considered, its noise levels are below the elevated (i.e. 60 decibels (dB)) noise levels shown in the noise contour maps. Streets were determined to be major thoroughfares based on the Consolidated Transportation Planning Maps from the City of Houston's Planning & Development Dept.
	Noise levels at 1270 Hopper Rd. have been calculated at 68 dB which falls into HUD'S NORMALLY UNACCEPTABLE range. Noise mitigation will be required during construction. For Normally Unacceptable Noise Zone (NUNZ) projects: Mitigation measures to ensure interior noise levels under 45 dB as confirmed by an architect or acoustical engineer will be required, with exterior noise levels for noise sensitive areas (i.e. areas where people congregate/relax like back yards, front porches, etc.) reduced to under 65 dB if feasible. These requirements will be a condition of receiving federal funds, and the project will be subject to HUD liability if these conditions are not met, penalties including but not limited to the payback of federal funds may be issued. The noise measurements performed by the architect/acoustical engineer shall include the use of HUD's Sound Transmission Classification Assessment Tool (STraCAT) web-based tool to determine noise levels and appropriate measures for mitigation. More information on the STraCAT tool can be found at: https://www.hudexchange.info/stracat/ (link to tool); https://www.hud.gov/sites/documents/ENV_USERGUIDE_STRACAT.PDF (user guide).
	Noise mitigation will be required during construction to reduce the internal noise level to 45 decibels. The noise mitigation will include, but is not limited to, STC rated material to comply with desired 45 decibel assembly. The

contractor will furnish the certified documentation of sound attenuation rating for the record of this property. This amount of attenuation can be achieved presuming the use of insulating windows with STC-30 ratings, solid core doors with perimeter weather-stripping, attic insulation equivalent to R-13 or
more and brick façade.

Preparer Signature:

David Alfaro

Date: 5/8/2024

Name/Title/Organization: David Alfaro, Environmental Investigator IV, City of Houston, Housing & Community Development Dept.


Reviewer Official Signature:

 Malissa Lahey
 Date:
 5/8/2024

 Name/Title: Melissa Lahey, Environmental Manager, City of Houston, Housing & Community

 Development Dept.

This original, signed document and related supporting material must be retained on file by the Responsible Entity in an Environmental Review Record (ERR) for the activity/project (ref: 24 CFR Part 58.38) and in accordance with recordkeeping requirements for the HUD program(s).




Docusign Envelope ID: 10C13B37-8068-4DAA-9622-A86ACA04641A National Flood Hazard Layer FIRMette




Legend

95°22'28"W 29°53'1"N SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT Without Base Flood Elevation (BFE) Zone A. V. A9 i S S With BFE or Depth Zone AE, AO, AH, VE, AR SPECIAL FLOOD FEE HAZARD AREAS **Regulatory Floodway** 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average Zone depth less than one foot or with drainage areas of less than one square mile Zone X Future Conditions 1% Annual Chance Flood Hazard Zone X Area with Reduced Flood Risk due to Levee. See Notes. Zone X OTHER AREAS OF FLOOD HAZARD Area with Flood Risk due to Levee Zone D 71.11 FEE HARRIS COUNTY NO SCREEN Area of Minimal Flood Hazard Zone X UNINCORPORATED AREAS Effective LOMRs 480287 OTHER AREAS Area of Undetermined Flood Hazard Zone D - — – – Channel, Culvert, or Storm Sewer GENERAL STRUCTURES LIIII Levee, Dike, or Floodwall 20.2 Cross Sections with 1% Annual Chance 17.5 Water Surface Elevation **Coastal Transect** 72.5 FEET Mase Flood Elevation Line (BFE) CITY OF HOUSTON Limit of Study Jurisdiction Boundary 480296 **Coastal Transect Baseline** OTHER 48201C0490L **Profile Baseline** FEATURES Hydrographic Feature eff. 6/18/2007 **Digital Data Available** No Digital Data Available MAP PANELS Unmapped 72.5 FEET (H) The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location. This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 5/6/2024 at 3:00 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or 0.2 PCT ANNUAL CHANCE FLOOD HAZARD become superseded by new data over time. Zone X This map image is void if the one or more of the following map 72.5 FEE elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for 95°21'50"W 29°52'30"N Feet 1:6,000 unmapped and unmodernized areas cannot be used for regulatory purposes. 1,000 250 500 1.500 2,000

Basemap Imagery Source: USGS National Map 2023





SITE-SPECIFIC FIELD CONTAMINATION & ECOLOGICAL CHECKLIST							
Completing the form requires a site visit by the preparer. The preparer should be sure to observe the property by walking through the property and the building(s) and other structures on the property to the extent possible and observing all adjoining* properties. PREPARER MUST COMPLETE CHECKLIST IN ITS ENTIRITY							
Date of Visit: 5/7/2024	Time: 10:02	Weather Condition			varn	1	
Program Name: Home Repair F	rogram						
Project Name: Single Family H	ome						
 Structure demolition opera If yes, is there potential for Pipeline and underground u De-watering. Purchase of new ROW or ea Trenching, drilled shafts, cu 	 Does the project include any of the following activities? Include all that apply. Structure demolition operations or structure modifications. If yes, is there potential for the building to contain asbestos or lead-based paint? Yes No Pipeline and underground utility installation or adjustments. De-watering. Purchase of new ROW or easement. Trenching, drilled shafts, cuts or other excavations. Project Location/Address: 1270 Hopper Rd, Houston, TX 77037 						
Property Owner: Dana Jones							
Attach the following, as approp Photographs of site and su		□Maps (street,	topogra	phic, ae	erial,	site map, et	:c.)
	UESTION			OBS	SER'	VATION	
Is there evidence		ollowing?		OBS UBJEC ^T OPERT	r	VATION ADJOININ PROPERTI	
Is there evidence Is the property or any adjoining prior use, as a gasoline station, facility, dry cleaners, photo devi	e of any of the for roperty currently us motor vehicle rep veloping laborator	ed, or has evidence o air facility, printing ry, junkyard, or as a	of YES		r	ADJOININ	
Is there evidence Is the property or any adjoining pupior use, as a gasoline station, facility, dry cleaners, photo dev waste treatment, storage, dispose Are there any damaged or discard industrial batteries, pesticides, containers greater than 5 gal in ve	e of any of the for roperty currently us motor vehicle rep veloping laborator osal, processing of ded automobile(s) paints, or other c olume or 50 gal in t	ed, or has evidence of pair facility, printing y, junkyard, or as a pr recycling facility? , automotive or hemicals in individua	of YES NO UNI YES	UBJEC OPERT S	Γ Ύ	ADJOININ PROPERTI YES NO	ES □ ×
Is there evidence Is the property or any adjoining pupior use, as a gasoline station, facility, dry cleaners, photo devi waste treatment, storage, dispo Are there any damaged or discard industrial batteries, pesticides, containers greater than 5 gal in vi- on or used at the property or adjo Are there any industrial drums (the herbicides or pesticides located	e of any of the for roperty currently us motor vehicle rep veloping laborator osal, processing of ded automobile(s) paints, or other c olume or 50 gal in t ining properties? ypically 55 gal) or s d on the property or	ed, or has evidence of air facility, printing y, junkyard, or as a pr recycling facility? , automotive or hemicals in individua he aggregate, stored acks of chemicals, adjoining properties?	of YES NO UNI YES NO YES NO	UBJEC COPERT S KNOWN S KNOWN		ADJOININ PROPERTI YES NO UNKNOWN YES NO	
Is there evidence Is the property or any adjoining point use, as a gasoline station, facility, dry cleaners, photo devi waste treatment, storage, dispose Are there any damaged or discard industrial batteries, pesticides, containers greater than 5 gal in ve on or used at the property or adjose Are there any industrial drums (te	e of any of the for roperty currently us motor vehicle rep veloping laborator osal, processing of ded automobile(s) paints, or other c olume or 50 gal in t ining properties? ypically 55 gal) or s d on the property or e property or adjoin or that is of an unkr	eed, or has evidence of pair facility, printing ry, junkyard, or as a pr recycling facility? , automotive or hemicals in individua he aggregate, stored acks of chemicals, adjoining properties that nown origin?	of YES NO UNI YES NO UNI YES NO UNI YES NO	UBJEC COPERT S KNOWN S KNOWN S		ADJOININ PROPERTI YES NO UNKNOWN YES NO UNKNOWN	

	UNKNOWN		UNKNOWN	
Are there any <i>pits, ponds, or lagoons</i> located on the property or adjoining	YES		YES	
properties in connection with waste treatment or waste disposal?	NO	X	NO	X
	UNKNOWN		UNKNOWN	
Oil sheen or films on surface water, seeps, lagoons, ponds, or drainage	YES		YES	
basins?	NO	X	NO	X
	UNKNOWN		UNKNOWN	
Is there any stained soil, distressed vegetation and/or discolored water	YES		YES	
on the property or adjoining properties?	NO	X	NO	X
	UNKNOWN		UNKNOWN	
Are there any storage tanks, aboveground or underground (other than	YES		YES	
residential), located on the property or adjoining properties?	NO	X	NO	X
	UNKNOWN		UNKNOWN	
*Adjoining properties: Any real property or properties the border of which is contiguous or partially con be contiguous or partially contiguous with that of the property but for a street, road, or other public tho				ould
QUESTION	SUBJEC			١G
Is there evidence of any of the following?	PROPER		PROPERT	
Are there any vent pipes, fill pipes, or underground tank access ways	YES		YES	
visible on the property or adjoining properties?	NO	$\overline{\mathbf{X}}$	NO	\mathbf{X}
	UNKNOWN		UNKNOWN	
Are any flooring, drains, walls, ceilings, or grounds on the property or	YES		YES	
adjoining properties stained by substances (other than water) or emitting	NO	\mathbf{X}	NO	X
noxious or foul odors or odors of a chemical nature?	UNKNOWN		UNKNOWN	
Is the property served by a <i>private well or non-public water system</i> ? (If	YES			
yes, a follow-up investigation is required to determine if contaminants have	NO	\times		
been identified in the well or system that exceed guidelines applicable to the	UNKNOWN			
water system, or if the well has been designated contaminated by any				
government environmental/health agency.) Has the owner or occupant of the property been informed of the existence	YES		YES	
of past or current <i>hazardous substances or petroleum products or</i>	NO	\mathbf{X}	NO	\mathbf{X}
environmental violations with respect to the property or adjoining	UNKNOWN		UNKNOWN	
properties?	UNKINOWIN		UNKINOWIN	
Do the property or adjoining properties <i>discharge wastewater</i> (not	YES		YES	
including sanitary waste or storm water) onto the property or adjoining	NO	X	NO	X
properties and/or into a storm water system?	UNKNOWN		UNKNOWN	
Is there a <i>transformer, capacitor, or any hydraulic equipment</i> on the	YES		YES	
property or adjoining properties that are not marked as "non-PCB"?	NO	X	NO	X
If so, are there signs of leaking transformers oil on the ground?	UNKNOWN		UNKNOWN	
Are there injection wells, cisterns, sumps, dry wells flooring, drains, or walls	YES			
stained by substances other than water or emitting foul odors?	NO	$\mathbf{\Sigma}$		
	UNKNOWN			_
Surface dumping of trash, garbage, refuse, rubbish, debris, landfill,	YES		YES	
stockpiling, storage, etc?	NO	\boxtimes	NO	\mathbf{X}
Security fencing, protected areas, placards, warning signs?	YES		YES	
	NO	\square	NO	\mathbf{X}
Dood onimals possibly due to contemination?			UNKNOWN	
Dead animals possibly due to contamination?	YES			
		\square		
	UNKNOWN			

If answering "YES" or UNKNOWN" to any above ite Use photographs and maps to mark and identify co				
Is further evaluation warranted? YES I NO I				
Ecological Site Information				
General Site Description (residential, commercial, foreste				
The subject property is a single-family home in a resid apparent visible signs of on-site or off-site contamination, along the front of the property was free and clear. Th commercial facilities with no signs of industrial activity. Th	and no unusual odors were r e surrounding properties we	noted. The drainage running ere single family homes or		
Water bodies present? If yes, describe (pond, lake, cree	, river, wetland, etc.):			
No				
Special or unique vegetation features?				
No				
Special wildlife habitat?				
No				
Observed wildlife:				
No				
Observed nests or potential nesting sites?				
No				
National, state, or locally designated park or natural rese	ve at, or adjacent to, the pro	oject site?		
Νο				
Other compliance factors identified on, or adjacent to, pro Historic age buildings Refineries Airports, run Commercial facilities Healthcare facilities So		ies		
Preparer of this form must complete		information.		
The site visit was completed by: David Alfaro	Phone Number: 832.459.8			
	Email: David.Alfaro@hous			
Title: Environmental Investigator IV	Agency: City of Houston, Housing & Community Development Department			
Address: 2100 Travis St. Houston, TX 77002	1 1			
Preparer represents that to the best of his/her knowledge the above statements and facts are true and correct and to the best of his/her actual knowledge no material facts have been suppressed, omitted or misstated.				
Signature: David Alfaro		5/7/2024		
		DRAFT HUD-R7-5-4-12		

1. §58.5(i) (2) Contamination and Toxic Substances

a. Is the property located within the search distances of any of the types of environmental contamination sources?

Standard Environmental Record Sources	Approximate Minimum Search Distance (mi)	Yes	No
Federal NPL Site List	1		\boxtimes
Federal Delisted NPL Site List	0.5		\boxtimes
Federal CERCLIS List	0.5		\boxtimes
Federal CERCLIS NFRAP Site List 0.5	0.5		\boxtimes
Federal RCRA CORRACTS Facilities List	1		\boxtimes
Federal RCRA Non-CORRACTS TSD Facilities List	0.5 Drog orty/A disining		\boxtimes
Federal RCRA Generators List	Property/Adjoining Properties		\boxtimes
Federal Institutional Control/Engineering Control Registries	Property Only		\boxtimes
Federal ERNS List	Property Only		\boxtimes
State- and Tribal-Equivalent NPL	1		\boxtimes
State- and Tribal-Equivalent CERCLIS	0.5		\boxtimes
State and Tribal Landfill and/or Solid Waste Disposal Site Lists	0.5		\boxtimes
State and Tribal Leaking Storage Tank Lists	0.5	\bowtie	
State and Tribal Registered Storage Tank Lists	Property/Adjoining Properties		\boxtimes
State and Tribal Institutional Control/Engineering Control Registries	Property Only		\boxtimes
State and Tribal Voluntary Cleanup Sites	0.5		\boxtimes
State and Trial Brownfield Sites	0.5	\boxtimes	

b. Did a visual inspection of the site show the following?

	Yes	No
Distressed vegetation		\boxtimes
Vent or Fill Pipes		
Storage Oil Tanks or Questionable Containers		

	Yes	No
Pits, Ponds or Lagoons		\boxtimes
Stained Soil or Pavement (other than water stains)		\boxtimes
Pungent, Foul or Noxious Odors		\boxtimes
Dumped Material or Soil, Mounds of Dirt, Rubble, Fill, etc.		\boxtimes

c. Has the property ever been used for any of the following types of uses?

Gas Station	Yes	No	Vehicle Repair Shop	Yes	No
Car Dealership		\boxtimes	Auto Garage		\boxtimes
Depot		\boxtimes	Commercial Printing Facility		\boxtimes
Industrial or commercial warehouses		\boxtimes	Dry Cleaners		\boxtimes
Photo Developing Laboratory		\boxtimes	Hospital		\boxtimes
Junkyard or landfill			Agricultural/Farming Operations		
Tannery		\boxtimes	Live stock Operations		\boxtimes

d. Does the project have an underground storage tank other than a residential fuel tank, or known or suspected to be contaminated by toxic chemicals or radioactive materials?

🗌 Yes 🖾 No

If No to all of the above, compliance with this section is complete. Mark box "A" on the Statutory Checklist for this authority.

If Yes to any of the above, a qualified environmental professional must undertake investigations necessary to ensure that the project is free of hazardous materials, contamination, toxic chemicals and gases, and radioactive substances such that there is no hazard which could affect the health and safety of occupants or conflict with the intended utilization of the property. Continue.

f. Could nearby toxic, hazardous or radioactive substances affect the health and safety of project occupants or conflict with the intended use of the property?
Yes or No

g. Are there unresolved concerns that could lead to the RE being determined to be a Potentially Responsible Party (PRP)?
Yes No

If Yes, continue.

If No, provide written documentation from a qualified environmental professional which documents that identified potential sources of contamination does not pose a hazard which would restrict the intended uses of the property or to the occupants.

- h. Was an ASTM Phase I Environmental Site Assessment (ESA) report completed for this project? (Note: HUD regulations do not require an ASTM Phase I ESA report for single family homes of 1-4 units. An ASTM Phase I ESA report is required for multifamily (5 or more units) and/or Non-residential properties.)
 Yes No
- Did the ASTM Phase I ESA or other documentation uncover any Recognized Environmental Conditions (RECs) or recommend a Phase II, special/specific Phase II, or recommend Phase III environmental site assessments?
 Yes No

If Yes, continue.

If No, compliance with this section is complete. Mark box "A" on the Statutory Checklist for this authority.

j. Do ESAs or other documentation conclude that nearby toxic, hazardous or radioactive substances could affect the health and safety of project occupants or conflict with the intended use of the property?

Yes or	No No
--------	-------

If Yes, continue below.

If No, compliance with this section is complete. Mark box "A" on the Statutory Checklist for this authority.

k. Did any of the ESA reports or other documentation identify the need to mitigate the environmental condition by removing, stabilizing or encapsulating the toxic substances in accordance with the requirements of the appropriate Federal, state or local oversight agency?

Yes No

If Yes, continue.

If No, compliance with this section is complete. Mark box "A" on the Statutory Checklist for this authority.

Can all adverse environmental conditions identified in any of the ESAs or other documentation be mitigated?
 Yes No

If Yes, compliance with this section is complete. List specific remedial actions or mitigations in the mitigation section of the Statutory Checklist, according to the requirements of the appropriate Federal, state, or local oversight agency. Mark box "B" on the Statutory Checklist for this authority.

If No, HUD cannot provide assistance for the project at this site.

Comments:

Cite and attach source documentation: (Maps showing project distance to contaminated sites. Phase I (ASTM) Report. All ESAs and mitigation plans performed for this project.)

For additional information see: HUD Information on Hazardous, Toxic or Radioactive Substances http://portal.hud.gov/hudportal/HUD?src=/program_offices/comm_planning/environment/review /hazardous EPA Envirofacts Data: http://www.epa.gov/enviro/ EPA Toxic Release Inventory (TRI): http://www.epa.gov/enviro/html/toxic_releases.html EPA Maps: http://www.epa.gov/emefdata/em4ef.home EPA CERCLIS/NPL – Superfund database: http://www.epa.gov/superfund/sites/query/basic.htm ATSDR "ToxFAQs" summaries about hazardous substances: http://www.atsdr.cdc.gov/toxfaqs/index.asp Right-To-Know Network: http://www.rtknet.org/



Query Home Customer Search RE Search ID Search Document Search TCEQ Home

Central Registry Query - Regulated Entity Search

Search for a person, organization, place, or thing that is of environmental interest to the TCEQ, where regulatory activities or interest to us occur or have occurred in the past.

! No results were found for the criteria you entered. Please try again. For hints on searching for Central Registry data, please see the <u>Search Hints</u> page.

tion 1: Enter a Regulated Entity Refe	rence Number (RN):
RN Number 🧐 :	(9 digits or RN + 9 digits)
Search	
ption 2: Complete one or more of thes	e fields:
Regulated Entity:	(Name or part of name 2-40 characters.)
Program: PETROLEUM	I STORAGE TANK NON REGISTERED 🗸
Program ID:	(Permit, registration, or other program identifier.)
ID Status:	✓ (ID status, only used if program or ID entered.)
Street Address 🧐 : HOPPER	(3-35 characters.)
City: HOUSTON	(Enter complete or partial city name, 3-30 characters.)
ZIP Code: 77037 (M	ust be numeric and 5 digits.)
County:	×



Central Registry Query - Regulated Entity Search

Search for a person, organization, place, or thing that is of environmental interest to the TCEQ, where regulatory activities or interest to us occur or have occurred in the past.

No results were found for the criteria you entered. Please try again. For hints on searching for Central Registry data, please see the <u>Search Hints</u> page.

Regulated Entity Search	
Option 1: Enter a Regulated Entity Ref	erence Number (RN):
RN Number 🧐 :	(9 digits or RN + 9 digits)
Search	
Option 2: Complete one or more of the	se fields:
Regulated Entity:	(Name or part of name 2-40 characters.)
Program: PETROLEU	M STORAGE TANK REGISTRATION
Program ID:	(Permit, registration, or other program identifier.)
ID Status:	✓ (ID status, only used if program or ID entered.)
Street Address 🧐 : HOPPER	(3-35 characters.)
City: HOUSTON	(Enter complete or partial city name, 3-30 characters.)
ZIP Code: 77037 (Must be numeric and 5 digits.)
County:	✓
	Search Clear

TCEQ Home

Document Search

Central Registry Query - Regulated Entity Search

Search for a person, organization, place, or thing that is of environmental interest to the TCEQ, where regulatory activities or interest to us occur or have occurred in the past.

Query Home

Customer Search

RE Search

ID Search

! No results were found for the criteria you entered. Please try again. For hints on searching for Central Registry data, please see the <u>Search Hints</u> page.

Regulated Entity Search-	
Option 1: Enter a Regulated E	intity Reference Number (RN):
RN Number 🧐 :	(9 digits or RN + 9 digits)
	Search
Option 2: Complete one or me	are of these fields:
option 2. complete one of mo	ore of these fields.
Regulated Entity:	(Name or part of name 2-40 characters.)
Program:	PETROLEUM STORAGE TANK NON REGISTERED V
Program ID:	(Permit, registration, or other program identifier.)
ID Status:	✓ (ID status, only used if program or ID entered.)
Street Address 🥑 :	CARBY (3-35 characters.)
City:	HOUSTON (Enter complete or partial city name, 3-30 characters.)
ZIP Code:	77037 (Must be numeric and 5 digits.)
County:	~
	Search Clear

TCEO Home

Search Results

Central Registry Query - Regulated Entity Information

Regulated Entity Information

RN Number: RN101749836 Name: CARBY PROPERTIES Primary Business: No primary business description on file. Street Address: 1106 CARBY RD, HOUSTON TX 77037 3535 County: HARRIS Nearest City: No near city on file. State: TX Near ZIP Code: 77037 Physical Location: No physical location description ON file.

Affiliated Customers - Current

Your Search Returned 1 Current Affiliation Records (View Affiliation History ...)

The Customer Name displayed may be different than the Customer Name associated to the Additional IDs related to the customer. This name may be different due to ownership changes, legal name changes, or other administrative changes.

|--|

CN Number	Customer Name	Customer Role(s)	Details
CN600942882	CARBY PROPERTIES	OWNER	

Industry Type Codes


Code	Classification	Name
No NA	ICS or SIC Codes	on file.

Permits, Registrations, or Other Authorizations

There are a total of 2 programs and IDs for this regulated entity. Click on a column name to change the sort order.

1-2 of 2 Records

Program 🔺	ID Type	ID Number	ID Status
PETROLEUM STORAGE TANK REGISTRATION	REGISTRATION	1928	INACTIVE
PETROLEUM STORAGE TANK STAGE II			



Central Registry Query - Regulated Entity Search

Search for a person, organization, place, or thing that is of environmental interest to the TCEO, where regulatory activities or interest to us occur or have occurred in the past.

. No results were found for the criteria you entered. Please try again. For hints on searching for Central Registry data, please see the Search Hints page.

-Regulated Entity Search	
Option 1: Enter a Regulated Entity Refer	ence Number (RN):
RN Number 🧐 :	(9 digits or RN + 9 digits)
Search	
Option 2: Complete one or more of these	e fields:
Regulated Entity:	(Name or part of name 2-40 characters.)
Program: PETROLEUM	STORAGE TANK NON REGISTERED V
Program ID:	(Permit, registration, or other program identifier.)
ID Status:	 (ID status, only used if program or ID entered.)
Street Address 🥹 : CARDIFF	(3-35 characters.)
City: HOUSTON	(Enter complete or partial city name, 3-30 characters.)
ZIP Code: 77037 (Mu	ist be numeric and 5 digits.)
County:	
	Search



Central Registry Query - Regulated Entity Search

Search for a person, organization, place, or thing that is of environmental interest to the TCEQ, where regulatory activities or interest to us occur or have occurred in the past.

No results were found for the criteria you entered. Please try again. For hints on searching for Central Registry data, please see the <u>Search Hints</u> page.

-Regulated Entity Search-	
Option 1: Enter a Regulated Entity Ref	erence Number (RN):
RN Number 🧐 :	(9 digits or RN + 9 digits)
Search	
Option 2: Complete one or more of the	se fields:
Regulated Entity:	(Name or part of name 2-40 characters.)
Program: PETROLEU	M STORAGE TANK REGISTRATION
Program ID:	(Permit, registration, or other program identifier.)
ID Status:	 ✓ (ID status, only used if program or ID entered.)
Street Address 🧐 : CARDIFF	(3-35 characters.)
City: HOUSTON	(Enter complete or partial city name, 3-30 characters.)
ZIP Code: 77037	Must be numeric and 5 digits.)
County:	✓
	Search Clear

Docusign Envelope ID: 10C13B37-8068-4DAA-9622-A86ACA04641A

Site Name: 1270 Hopper Rd, Houston, TX 77037 Location: 1270 Hopper Rd, Houston, TX 77037 Prepared for: David A Ref: 1270 Hopper Rd, Houston, TX 77037 Center Coordinates: 29.879243,-95.369138 Prepared Date: Mon May 06 2024 20:25:07 GMT+0000 (Coordinated Universal Time)

ENVIRONMENTAL RADIUS REPORT

ASTM E1527-21



environmental.netronline.com

Summary


Federal	< 1/4	1/4 - 1/2	1/2 -
Lists of Federal NPL (Superfund) sites	0	0	0
Lists of Federal Delisted NPL sites	0	0	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders	0	0	0
Lists of Federal CERCLA sites with NFRAP	0	0	0
Lists of Federal RCRA facilities undergoing Corrective Action	0	0	0
Lists of Federal RCRA TSD facilities	0	0	0
Lists of Federal RCRA generators	0	0	0
Federal institutional control/engineering control registries	0	0	0
Federal ERNS list	0	0	0
State	< 1/4	1/4 - 1/2	1/2 -
Lists of state and tribal Superfund equivalent sites	0	0	1
Lists of state and tribal hazardous waste facilities	0	0	0
Lists of state and tribal landfills and solid waste disposal facilities	0	0	0
Lists of state and tribal leaking storage tanks	2	2	0
Lists of state and tribal registered storage tanks	2	0	0
State and tribal institutional control/engineering control registries	0	0	0
Lists of state and tribal voluntary cleanup sites	0	0	0
Lists of state and tribal brownfields sites	1	0	0
Other	< 1/4	1/4 - 1/2	1/2 -
State and/or tribal lists of sites requiring further investigation / remediation	0	0	0
State list of Significant Environmental Hazards (SEH)	0	0	0
Lists of state and tribal mine sites requiring further investigation and/or remediation	0	0	0
State and/or tribal lists of spills and spill responses	0	0	0
State and/or tribal lists of emergency responses	0	0	0
State and/or tribal lists of dry cleaners	0	0	0
State and/or tribal lists of clandestine laboratory cleanups	0	0	0
State and/or tribal lists of scrap/used tire processing facilities	0	0	0
State and/or tribal lists of underground injection control sites	0	0	0
State and/or tribal listings of permitted drywells	0	0	0
Automobile salvage yards	0	0	0
Livestock Waste Control sites	0	0	0
Controlled Animal Feeding Operations (CAFOs)	0	0	0
State and/or tribal lists of registered aboveground storage tanks (ASTs)	0	0	0
C.A.A. Permitted Facilities	0	0	0
NPDES Permitted Facilities	0	0	0
Onsite Wastewater Treatment sites	0	0	0
State and/or tribal lists of permitted facilities	6	0	0
Resource Conservation and Recovery Act Information (RCRAInfo)	1	2	0
	0	0	0
	v		
U.S. EPA Enforcement, Compliance History Online (ECHO)	1	0	0
U.S. EPA Enforcement, Compliance History Online (ECHO) U.S. EPA Underground Storage Tanks (UST) U.S. EPA Toxic Substances Control Act (TSCA) database		0	0

environmental.netronline.com

Lists of state and tribal Superfund equivalent sites

TCEQ - STATE SUPERFUND

The State Superfund program addresses facilities that may constitute an imminent and substantial endangerment to public health and safety or the environment due to a release or threatened release of hazardous substances into the environment. The Texas Commission on Environmental Quality (TCEQ) publishes the list, or registry, of state Superfund sites annually. Sites with a score of 5.0 or above through the Hazard Ranking System may be referred from the Superfund Site Discovery and Assessment program or the Preliminary Assessment and Site Inspection program to be proposed to the state registry.



center: 29.879243,-95.369138

---- 0.5 Miles ---- 1.0 Miles



WASTE OIL TANK SERVICES


2010 HARTWICK RD Rem. Program: Superfund (SF) RN: RN100677244 EPA TXID: TXD490013844 Superfund ID: SUP153 Site Name: WASTE OIL TANK SERVICES Physical Address: 2010 HARTWICK RD Address Description: 2010 Hartwick, Houston, TX City: HOUSTON County: HARRIS ZIP: 77093 Region: REGION 12 - HOUSTON Web URL: http://www.tceq.texas.gov/remediation/superfund/state/wasteoil.html Latitude: 29.88448979 Longitude: -95.35405605 Distance From Center (Miles): 0.9732 Site Source: last updated 01-24-2024 from TCEQ-SSU-2023

environmental.netronline.com

Lists of state and tribal leaking storage tanks

TCEQ - LEAKING UNDERGROUND STORAGE TANK

The Petroleum Storage Tank (PST) State Lead Program is authorized by law to remediate situations where a release from a PST system has occurred using the Petroleum Storage Tank Remediation (PSTR) Fund. This data layer contains locations of leaking PSTs that have been reported to and investigated by the State of Texas.



center: 29.879243,-95.369138

1

---- 0.5 Miles ---- 1.0 Miles

CAMP 12 HARRIS COUNTY PRECINCT4

11801 W HARDY RD LPST ID: 108131 Site Name: CAMP 12 HARRIS COUNTY PRECINCT4 Address: 11801 W HARDY RD City: HOUSTON Distance From Center (Miles): 0.4515 Site Source: last updated 11-18-2021 from TCEQ-LUST

HARDY SHOP

2

3

1303 HOPPER RD

LPST ID: 91549 Site Name: HARDY SHOP Address: 1303 HOPPER RD City: HOUSTON Distance From Center (Miles): 0.1664 Site Source: last updated 11-18-2021 from TCEQ-LUST

MELROSE DRIVE IN GROCERY

12635 W HARDY RD LPST ID: 115730 Site Name: MELROSE DRIVE IN GROCERY Address: 12635 W HARDY RD City: HOUSTON Distance From Center (Miles): 0.2431 Site Source: last updated 11-18-2021 from TCEQ-LUST

WATKINS MOTOR LINES


550 CANINO RD

LPST ID: 106874 Site Name: WATKINS MOTOR LINES Address: 550 CANINO RD City: HOUSTON Distance From Center (Miles): 0.4842 Site Source: last updated 11-18-2021 from TCEQ-LUST environmental.netronline.com

Lists of state and tribal brownfields sites

TCEQ - INDUSTRIAL AND HAZARDOUS WASTE CORRECTIVE ACTION PROGRAM

The Texas Commission on Environmental Quality (TCEQ) Industrial and Hazardous Waste (IHW) Corrective Action Program administers the cleanup of sites contaminated from industrial and municipal hazardous and industrial nonhazardous wastes.



center: 29.879243,-95.369138

1

SITEWIDE

11422 E HARDY RD

IHWCA ID: T1812 Site Name: SITEWIDE Address: 11422 E HARDY RD City: HOUSTON Distance From Center (Miles): 0.1973 Site Source: last updated 11-18-2021 from TCEQ-HSWA ---- 0.5 Miles ---- 1.0 Miles



Waste Oil Tank Service

No further Superfund environmental response actions are required on this former waste oil collection and transfer facility in Houston, Harris County.

Site Background

The Waste Oil Tank Service site is located at 2010 Hartwick Road in an unincorporated area of Harris County that is enveloped by the city of Houston, and is approximately 0.5 acre in size. A waste oil collection and transfer facility operated at this site from approximately 1974 to 1985. In addition, paint thinner, transformer oil, lubricating oil, diesel fuel, compressor oil, crude slop, mineral spirits, methyl ethyl ketone, trichloroethylene, xylene, naphtha, spent acid solution, antifreeze, hydraulic oil, solvents with organic residues, and miscellaneous other chemicals were handled at the site. The site consisted of four large, upright tanks and one smaller tank in a diked area, two additional horizontal tanks, and more than sixty 55-gallon containers. The diked area and the drums contained contaminated liquid and sludge. Historically, the site accommodated a variety of tanks, tankers, and drums.

Superfund Actions Taken to Date

- October 16, 1987, a legal notice was published in the *Texas Register* (12 TexReg 3858) **proposing** the site to the state Superfund registry, and announcing that a public meeting to receive citizen comments would be held at the Pasadena Convention Center on November 19, 1987.
- January 22, 1988, a legal notice was published in the *Texas Register* (13 TexReg 427) **listing** the site on the state Superfund registry.
- September 1, 1993, effective date of the creation of the Texas Natural Resource Conservation Commission from the joining of the Texas Water Commission and the Texas Air Control Board and a portion of the Texas Department of Health.
- September 20, 1995, an immediate removal action was initiated by the potentially responsible party. A total of 58,476 gallons of oily water, oily water/sludge, rainwater and oil and water was removed from the site. A total of 748 cubic yards of soil, oily sludge and water, concrete and debris was also removed. A total of 65 55-gallon drums were cleaned, crushed and combined with the on-site debris and removed. A previously unreported 2,000-gallon underground storage tank was removed and cleaned and transported to a recycling center along with 67 used automobile tires.
- April 25, 1996, remedial investigation / feasibility study under way.
- September 30, 1996, the final report was approved, marking completion of the remedial investigation / feasibility study phase.
- March 10, 1997, a supplemental removal action of 80 cubic yards of soil was conducted in an attempt to remove the surface soils down to background levels.
- August 8, 1997, a legal notice was published in the *Texas Register* (22 TexReg 7418) proposing to **delete** the site from the state Superfund registry in accordance with 30 TAC §335.344(c), and inviting public comment on the determination that the site no longer presented an imminent and substantial endangerment to public health and safety or the environment. No further remedial action planned.

- October 31, 1997, a legal notice was published in the *Texas Register* (22 TexReg 10819-10820) officially deleting the Waste Oil Tank Service site from the state Superfund registry in accordance with 30 TAC §335.344(c). No challenges or comments were received to the determination that the site no longer presents an imminent and substantial endangerment to public health and safety or the environment. No further remedial action planned. The site is usable for residential development.
- September 1, 2002, effective date of the name change from Texas Natural Resource Conservation Commission (TNRCC) to Texas Commission on Environmental Quality (TCEQ).

Back to Top

Remediation Home

Texas Risk Reduction Program

Superfund

Leaking Petroleum Storage Tank Cleanups

Voluntary Cleanup Program

Innocent Owner/Operator Program

Industrial and Hazardous Waste Corrective Action

Dry Cleaner Remediation Program

How are we doing? Take our customer satisfaction survey

Site Specific Information

EPA ID: TXD490013844 Location: Houston, Harris County Site Status: CLEANUP COMPLETE - NO FURTHER SUPERFUND ENVIRONMENTAL RESPONSE ACTIONS ARE REQUIRED Type of Facility: Waste Oil Collection and Transfer Category: Deleted from Registry Media Affected: Soil, Surface Water Latitude: 29°53'00"N Longitude: -95°21'14"W Hazard Ranking Score (HRS): 11.2 Contaminants at time of HRS: Heavy Metals, Hydrocarbons TCEQ Region: Houston - 12 Funded by: Potentially Responsible Parties

Contact Information

Superfund Program Contact Scott Settemeyer Phone: 512-239-3429 or 1-800-633-9363 E-mail: **superfnd@tceq.texas.gov**

TCEQ Central File Room

12100 Park 35 Circle Building E First Floor Room 103 Austin, TX 78753 512-239-2900 512-239-1850 (fax) **cfrreq@tceq.texas.gov**



Central Registry

The Customer Name displayed may be different than the Customer Name associated to the Additional IDs related to the customer. This name may be different due to ownership changes, legal name changes, or other administrative changes.

Detail of: IHW Corrective Action ID Number T1812

For: **SITEWIDE (RN104641303 ...)**

No physical location description on file.

ID Number Status: INACTIVE

Responsible Parties: **US Department of Veterans' Affairs (CN602854846 ...)** Since 11/22/2002

Mailing Address: 6900 ALMEDA RD HOUSTON, TX 77030 -4200

Legal	Description	Start Date	Start Date End Date		Status	Status Date
T1812	IHW CORRECTIVE ACTION	11/22/2002		CLEANUP	INACTIVE	02/03/2004

Tracking No.	Туре	Value	Start Date	End Date
9317493	ADMINISTRATIVE STATUS	INACTIVE	02/03/2004	
10253690	PROJECT MANAGER	LBECKLEY	12/20/2001	

Physical	Description	Start Date	Туре	Status	Status Date
US DEPARTMENT OF VETERANS AFFAIRS HOUSTON		01/01/1901	IHW CA	COMPLETED WORKLOAD	02/03/2004

Tracking No.	Туре	Value	Start Date	End Date
9338759	PROJECT PHASE	COMPLETED WORKLOAD	02/03/2004	
1210665	CURRENT FACILITY TYPE	PROPERTY SALE/REDEVELOPMENT	01/01/1901	
9328842	SOURCE OF RELEASE	SITEWIDE	01/01/1901	

Site Help | Disclaimer | Web Policies | Accessibility | Our Compact with Texans | TCEQ Homeland Security

Contact Us | Central Registry | Search Hints | Report Data Errors

Statewide Links: Texas.gov | Texas Homeland Security | TRAIL Statewide Archive | Texas Veterans Portal

© 2002 - 2024 Texas Commission on Environmental Quality Last Modified 2024-03-05 - Production v2.2.0



Central Registry

The Customer Name displayed may be different than the Customer Name associated to the Additional IDs related to the customer. This name may be different due to ownership changes, legal name changes, or other administrative changes.

Detail of: IHW Corrective Action ID Number T1812

For: **SITEWIDE (RN104641303 ...)**

No physical location description on file.

ID Number Status: INACTIVE

Responsible Parties: **US Department of Veterans' Affairs (CN602854846 ...)** Since 11/22/2002

Mailing Address: 6900 ALMEDA RD HOUSTON, TX 77030 -4200

Related Information:

Correspondence Tracking Corrective Action Information


There is no information related to this Corrective Action in the following categories:


Commissioners' Actions Effective Enforcement Orders Criminal Convictions Proposed Enforcement Orders Complaints Discharges Emergency Response Events Emission Events Fish Kills Other Incidents Investigations Periodic Reports


Site Help | Disclaimer | Web Policies | Accessibility | Our Compact with Texans | TCEQ Homeland Security

Contact Us | Central Registry | Search Hints | Report Data Errors Statewide Links: Texas.gov | Texas Homeland Security | TRAIL Statewide Archive | Texas Veterans Portal

© 2002 - 2024 Texas Commission on Environmental Quality Last Modified 2024-03-05 - Production v2.2.0










RADON | RADON TESTS FROM LABS | MEDIAN PRE-MITIGATION RADON LEVEL IN TESTED BUILDINGS OVER A 10-YEAR PERIOD | TEXAS | 2008-2017







RADON | RADON TESTS FROM LABS | MEAN PRE-MITIGATION RADON LEVEL IN TESTED BUILDINGS OVER A 10-YEAR PERIOD | TEXAS | 2008-2017



noreply@thc.state.tx.us
HCD - Environmental; reviews@thc.state.tx.us
Single Family Home Repair
Wednesday, May 8, 2024 7:37:01 AM

[This message came from outside the City of Houston email system. Please be careful while clicking links, opening attachments, or replying to this email.]



Re: Project Review under Section 106 of the National Historic Preservation Act THC Tracking #202410162 Date: 05/08/2024 Single Family Home Repair 1270 Hopper Rd Houston,TX 77037

Description: Reconstruction of single family home

Dear HCDD Environmental:

Thank you for your submittal regarding the above-referenced project. This response represents the comments of the State Historic Preservation Officer, the Executive Director of the Texas Historical Commission (THC), pursuant to review under Section 106 of the National Historic Preservation Act.

The review staff, led by Charles Peveto, has completed its review and has made the following determinations based on the information submitted for review:

Above-Ground Resources

• Property/properties are not eligible for listing in the National Register of Historic Places.

We look forward to further consultation with your office and hope to maintain a partnership that will foster effective historic preservation. Thank you for your cooperation in this review process, and for your efforts to preserve the irreplaceable heritage of Texas. If the project changes, or if new historic properties are found, please contact the review staff. If you have any questions concerning our review or if we can be of further assistance, please email the following reviewers: charles.peveto@thc.texas.gov.

This response has been sent through the electronic THC review and compliance system (eTRAC). Submitting your project via eTRAC eliminates mailing delays and allows you to check the status of the review, receive an electronic response, and generate reports on your submissions. For more information, visit <u>http://thc.texas.gov/etrac-system</u>.

Sincerely,



for Bradford Patterson Chief Deputy State Historic Preservation Officer

Please do not respond to this email.



CITY OF HOUSTON-

Housing & Community Development Department

John Whitmire

Mayor

Michael C. Nichols Director 2100 Travis, 9th Floor Houston, Texas 77002

T. (832) 394-6200 F. (832) 395-9662 www.houstontx.gov/housing

May 7, 2024

Mr. Charles Peveto, Chief Project Reviewer Texas Historical Commission P. O. Box 12276 Austin, Texas 78711-2276

Re: Section 106 Review Reconstruction of Single-Family Home 0.18 acre of land located at 1270 Hopper Rd. Houston, Texas 77037

Dear Mr. Peveto:

Please accept and review the enclosed information on the above referenced project to be undertaken by the City of Houston. Environmental review procedures for federal programs issued in 24 CFR 58 require that we carry out this project in accordance with the Section 106 Review for the environmental process. We are looking for architectural and archaeological review and comment on this site.

This project entails reconstruction of a single-family home on a 0.18 acre (7,955 sq. ft.) of land on the south side of Hopper Rd. and west of Hardy St. This site is currently an existing single-family home. Bing aerial maps identify the site as "1270 Hopper Rd". Google maps identify roughly the same point as "1270 Hopper Rd.". The site includes HCAD # 0942330000003. This project has been designated as a reconstruction, which includes but is not necessarily limited to removal and replacement of the home's interior, and any necessary exterior work as well.

Enclosed for your review and comment is a site map, site photographs, an HCAD report, a City of Houston Planning & Development Historical District map, an aerial map, and a historical atlas map for the above-referenced federal project. This site is not located in an historical survey area and is not located within an officially designated historic district in Houston, Texas. We anticipate that your office concurs with our determination that the implementation of this project will not adversely affect a historic property.

If any additional information is needed, please contact Melissa Lahey, (832) 394-6397; Matt Jenkins at (832) 394-6183, David Alfaro at (832) 394-6056 or by e-mail at hcdenvironmental@houstontx.gov (also cc Laura.Serrano@houstontx.gov).

Sincerely,


Melissa Lahey

Melissa Lahey U Environmental Manager Real Estate Compliance Division

ML: DA Attachments:


TEXAS HISTORIC SITES ATLAS


MAP • SEARCH • ADVANCED SEARCH • DOWNLOADS • ABOUT ATLAS



sri Community Maps Contributors, City of Houston, HPB, Texas Parks & Wildlife, @ OpenStreetMap, Microsoft, CONANP, Esri, TomTom, Garmin, Foursquare, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA, USFWS | Texas Historical Commission, History Programs Division, Historic Resource ... Powered by Esri







Tax Year: 2024

E. Print

HARRIS CENTRAL APPRAISAL DISTRICT REAL PROPERTY ACCOUNT INFORMATION 0942330000003

	Owner and Property Information												
	Owner Name & SANDERS DANA JONES Mailing Address: 1270 HOPPER RD HOUSTON TX 77037-3527						I Description: erty Address:	LT 3 BLK 6 MELROSE PARK SEC 2 1270 HOPPER RD HOUSTON TX 77037					
State Class Code	Land Use Code		Total Living Area	Neighborhood	Neighbor Grou		Market Area		Map Facet	Key Map [®]			
A1 Real, Residential, Single- Family	1001 Residential Improved	itial SF	1,544 SF	7064.04	1513	3	151 - Liberty/Kashmere/ Gardens	Houston/Croyden	5362B	413Q			

Value Status Information							
Value Status	Notice Date	Shared CAD					
Noticed	04/19/2024	No					

Exemptions and Jurisdictions

Exemption Type	Districts	Jurisdictions	Exemption Value	ARB Status	2023 Rate	2024 Rate
Residential Homestead (Multiple)	001	HOUSTON ISD	131,769	Not Certified	0.868300	
	040	HARRIS COUNTY	131,769	Not Certified	0.350070	
	041	HARRIS CO FLOOD CNTRL	131,769	Not Certified	0.031050	
	042	PORT OF HOUSTON AUTHY	131,769	Not Certified	0.005740	
	043	HARRIS CO HOSP DIST	131,769	Not Certified	0.143430	
	044	HARRIS CO EDUC DEPT	131,769	Not Certified	0.004800	
	048	HOU COMMUNITY COLLEGE	131,769	Not Certified	0.092231	
	061	CITY OF HOUSTON	131,769	Not Certified	0.519190	
Texas law prohibits us from displayi	na reside	ntial photographs, sketche	s, floor plans, or	information	indicating t	he age of

Texas law prohibits us from displaying residential photographs, sketches, floor plans, or information indicating the age of a property owner on our website. You can inspect this information or get a copy at HCAD's information center at 13013 NW Freeway.

	Valuations										
Value as	s of January 1, 202	23	Value as	s of January 1, 202	.4						
	Market	Appraised		Market	Appraised						
Land	42,996		Land	42,996							
Improvement	108,265		Improvement	110,964							
Total	151,261	119,790	Total	153,960	131,769						

					Land	ג						
	Market Value Land											
Line	Description	Site Code	Unit Type	Units	Size Factor	Site Factor	Appr O/R Factor	Appr O/R Reason	Total Adj	Unit Price	Adj Unit Price	Value
1	1001 Res Improved Table Value	SF1	SF	7,000	1.00	1.00	1.00		1.00	5.75	5.75	40,250.00

Land

2	1001 Res Improved Table Value	SF3	SF	955	1.00	0.50	1.00		0.50	5.75	2.88	2,746.00
---	----------------------------------	-----	----	-----	------	------	------	--	------	------	------	----------

			Building			
Building	Year Built	Туре	Style	Quality	Impr Sq Ft	Building Details
1 1962 Residential Single Family		Residential 1 Family	Average	1,544 *	Displayed	

* All HCAD residential building measurements are done from the exterior, with individual measurements rounded to the closest foot. This measurement includes all closet space, hallways, and interior staircases. Attached garages are not included in the square footage of living area, but valued separately. Living area above *attached* garages is included in the square footage living area of the dwelling. Living area above *detached* garages is not included in the square footage living area of the dwelling. Living area above *detached* garages is not included in the square footage living area of the dwelling. Living area above *detached* garages is not included in the square footage living area of the dwelling. This method is used on all residential properties in Harris County to ensure the uniformity of square footage of living area measurements district-wide. There can be a reasonable variance between the HCAD square footage and your square footage measurement, especially if your square footage measurement to the inch.

Βι								
Building Data								
Element	Detail							
Cond / Desir / Util	Average							
Foundation Type	Slab							
Grade Adjustment	С							
Heating / AC	Central Heat/AC							
Physical Condition	Average							
Exterior Wall	Frame / Concrete Blk							
Element	Units							
Room: Total	5							
Room: Half Bath	1							
Room: Full Bath	1							
Room: Bedroom	3							

ding Details	(1)	
	Building Areas	
	Description	Area
	ONE STORY FRAME PRI	484
	BASE AREA PRI	1,060
	OPEN FRAME PORCH PRI	60

Extra Features

Line	Description	Quality	Condition	Units	Year Bulit						
1	Frame Utility Shed	Average	Average	169.00	2013						



Site Specific Photo Documentation Report

Program: Single Family Home Repair Program (SFHR)
Project Name: SFHR Tier III Reconstruction/New Construction
Project Location/Address: 1270 Hopper Rd, Houston, TX 77037
Date of Photos: May 7, 2024
Prepared By: David Alfaro



View from Hopper St. Front of subject property facing south.



View from Hopper St. Left side of subject property facing southeast.




View from Hopper St. Right side of subject property facing southwest.



View from Hopper St. Front of subject property facing south.



View from Hopper St. Left side of subject property facing southeast.



Historic Districts	12,Freeland Historic District	
1,Courtland Place Historic District	13,Shadow Lawn Historic District	City of Houston
2,Main Street/Market Square Historic District	14,Audubon Place Historic District	Historic Districts
3,West Eleventh Place Historic	15,Boulevard Oaks Historic District	
4,Westmoreland Historic District	16,First Montrose Commons Historic District	
5,Old Sixth Ward Historic District	17,Houston Heights South Historic District	HOUSING AND COMMUNITY DEVELOPMENT
6,Avondale East Historic District	18,Woodland Heights Historic District	
7,Norhill Historic District	19,Glenbrook Valley Historic District	
8,Broadacres Historic District	20,Germantown Historic District	Data Sources: Housing & Community Development Department; and the City of Houston GIS.
9,Avondale West Historic District	21,Starkweather Historic District	Disclaimer: All data is prepared and made available for general reference purposes only and should not be used or relied upon for specific applications, without independent verification. All
10,Houston Heights West Historic District	22,High First Ward Historic District	data is best available at time of figure production. The City of Houston neither represents, nor warrants the data accuracy, or completeness, nor will the City of Houston accept liability of any kind in conjunction with its use.
11,Houston Heights East Historic District	23,Brunner-Harmonium Historic District	220127_1021

Emancipation Avenue/Main Street

Produced: 2/3/2022

Home (/) > Programs (/programs/) > Environmental Review (/programs/environmentalreview/) > DNL Calculator

DNL Calculator

The Day/Night Noise Level Calculator is an electronic assessment tool that calculates the Day/Night Noise Level (DNL) from roadway and railway traffic. For more information on using the DNL calculator, view the Day/Night Noise Level Calculator Electronic Assessment Tool Overview (/programs/environmental-review/daynight-noise-level-electronic-assessment-tool/).

Guidelines

- To display the Road and/or Rail DNL calculator(s), click on the "Add Road Source" and/or "Add Rail Source" button(s) below.
- All Road and Rail input values must be positive non-decimal numbers.
- All Road and/or Rail DNL value(s) must be calculated separately before calculating the Site DNL.
- All checkboxes that apply must be checked for vehicles and trains in the tables' headers.
- **Note #1:** Tooltips, containing field specific information, have been added in this tool and may be accessed by hovering over all the respective data fields (site identification, roadway and railway assessment, DNL calculation results, roadway and railway input variables) with the mouse.
- **Note #2:** DNL Calculator assumes roadway data is always entered.

DNL Calculator

Site ID	1270 Hopper Rd, Houston, TX 77037
Record Date	05/07/2024
User's Name	David Alfaro

Road # 1 Name:	Hardy Toll Rd.	

Road #1

Vehicle Type	Cars 🗹	Medium Trucks 🗹	Heavy Trucks 🗹
Effective Distance	628	628	628
Distance to Stop Sign			
Average Speed	65	65	65
Average Daily Trips (ADT)	62853	7394	3697
Night Fraction of ADT	15	15	15
Road Gradient (%)			1
Vehicle DNL	61	61	65
Calculate Road #1 DNL	68	Reset	

Rail # 1

Train Type	Electric 🗌	Diesel 🗹
Effective Distance		664
Average Train Sneed		45

листиде ттаптореса			
Engines per Train		2	
Railway cars per Train		50	
Average Train Operations (ATO)		15	
Night Fraction of ATO		38	
Railway whistles or horns?	Yes: 🗌 No:		Yes: 🗆 No: 🗹
Bolted Tracks?	Yes: 🗌 No:		Yes: 🗹 No: 🗌
Train DNL	0	57	
Calculate Rail #1 DNL	57	Reset	
Add Road Source Add Rail Source			
Airport Noise Level	40		
Loud Impulse Sounds?	OYe	s ONo	
Combined DNL for all Road and Rail sources	68		
Combined DNL including Airport	68		
Site DNL with Loud Impulse Sound			
Calculate Reset			

Mitigation Options


If your site DNL is in Excess of 65 decibels, your options are:

- No Action Alternative: Cancel the project at this location
- Other Reasonable Alternatives: Choose an alternate site
- Mitigation
 - Contact your Field or Regional Environmental Officer (/programs/environmentalreview/hud-environmental-staff-contacts/)
 - Increase mitigation in the building walls (only effective if no outdoor, noise sensitive areas)
 - Reconfigure the site plan to increase the distance between the noise source and noisesensitive uses
 - Incorporate natural or man-made barriers. See *The Noise Guidebook* (/resource/313/hud-noise-guidebook/)
 - Construct noise barrier. See the Barrier Performance Module (/programs/environmental-review/bpm-calculator/)


Tools and Guidance


Day/Night Noise Level Assessment Tool User Guide (/resource/3822/day-night-noise-levelassessment-tool-user-guide/)

Day/Night Noise Level Assessment Tool Flowcharts (/resource/3823/day-night-noise-levelassessment-tool-flowcharts/)









U. S. DOT CROSSING INVENTORY FORM

DEPARTMENT OF TRANSPORTATION


FEDERAL RAILROAD ADMINISTRATION

OMB No. 2130-0017


Instructions for the initial reporting of the following types of new or previously unreported crossings: For public highway-rail grade crossings, complete the entire inventory Form. For private highway-rail grade crossings, complete the Header, Parts I and II, and the Submission Information section. For public pathway grade crossings (including pedestrian station grade crossings), complete the Header, Parts I and II, and the Submission Information section. For Private pathway grade crossings, complete the Header, Parts I and II, and the Submission Information section. For grade-separated highway-rail or pathway crossings (including pedestrian station crossings), complete the Header, Part I, and the Submission Information section. For changes to existing data, complete the Header, Part I Items 1-3, and the Submission Information section, in addition to the updated data fields. Note: For private crossings only, Part I Item 20 and Part III Item 2.K. are required unless otherwise noted. An asterisk * denotes an optional field.												
A. Revision Date		B. Reporting A	gency		ason for Upo	•	elect only	one)			D. DOT Crossing	
(<i>MM/DD/YYYY</i>) 06 / 19 / 2020		🗷 Railroad	🗆 Tran		-	□ New		Closed	🗆 No Train	🗆 Quiet	Inventory Number	
00 / 19 / 2020		□ State	🗆 Othe	Data		Crossing ∃Date		Change in Drimony	Traffic	Zone Update	e 427247M	
					•	hange		☐ Change in Primary Derating RR	Correction		427247101	
				Part I: Lo		-	-	tion Informatio				
1. Primary Operating	Railroa	ıd			2. Sta				3. County			
Union Pacific Railro	oad Co	mpany [UP]			TEX				HARRIŠ			
4. City / Municipality	'			t /Road Nam E YORK R	ne & Block N	umber			6. Highway Ty	ype & No.		
□ Near HOUST	ON			/Road Name			_I I * (Bloc	k Number)	ST 0000			
7. Do Other Railroad	s Opera	te a Separate T			,	8.		Railroads Operate O	Ver Your Track	at Crossing?	Yes 🛛 No	
If Yes, Specify RR			,	,		-	f Yes, Spe	cify RR				
9. Railroad Division o	•	n	10. Railroad					nch or Line Name			ost 25.440	
□ None HOUS	FON		□ None	Palestine			Non 🗹				nn.nnn) (suffix)	
13. Line Segment *		14. Near Station	est RR Time	table	15. Parei	nt RR (if applicat	ole)	16. Crossii	ng Owner (if app	plicable)	
		Station			🖿 N/A				□ N/A	UP		
17. Crossing Type	18. Cr	ossing Purpose	19. Cross	ing Position	20. Pu	blic Acc	ess	21. Type of Train	- 1 -		22. Average Passenger	
	🗷 Hig	,	🗆 At Gra		()	ate Cro	ssing)	Freight	🗆 Transi	-	Train Count Per Day	
Public Private		hway, Ped. tion, Ped.	RR Un		□ Yes □ No		Intercity Passenger Share Commuter Touris			ed Use Transit ist/Other Number Per Day 0		
23. Type of Land Use		tion, red.		-						() Other		
□ Open Space	🗆 Farn	n 🗆 Resi	dential	🗷 Comme		Indu:		Institutional	🗆 Recreatio	onal 🗆 R	R Yard	
24. Is there an Adjac	ent Cros	ssing with a Sep	arate Numb	er?	25	. Quiet	Zone (Fl	RA provided)				
🗆 Yes 🗷 No 🛛 If	Voc Dro	vide Crossing N	umbor			No 🗆	7 7 4 U r	🗆 Partial 🛛 Chica	an Excused	Date Establi	shad	
26. HSR Corridor ID	res, Pro		ude in decim	al degrees				le in decimal degrees	•		at/Long Source	
				•	207020							
	_⊠ N/A	(WGS84	std: nn.nnn	nnnn) ^{29.8}	3707230	(W	GS84 std.	-nnn.nnnnnnn) ⁻⁹⁵	.3648950	🗶 Ac	tual 🗌 Estimated	
30.A. Railroad Use	*						31.A. State Use *					
30.B. Railroad Use	*						31.B. State Use *					
30.C. Railroad Use	*						31.C. State Use * State Phone# updated - date updated: 2018-08-16					
30.D. Railroad Use	*						31.D. State Use *					
32.A. Narrative (Rai	lroad U	se) *					32.B. I	Narrative (State Use)	*			
33. Emergency Notifi	ication ⁻	Telephone No. (posted)	34. Railr	oad Contact	(Telep	hone No.		35. State Cor	ntact (Telephon	e No.)	
800-848-8715				402-54	4-3721				512-416-26	512-416-2635		
					Part II: R	ailroa	d Info	mation				
1. Estimated Number	of Daily	/ Train Moveme	nts									
1.A. Total Day Thru T	rains		otal Night Th	ru Trains	1.C. Total S	witchin	g Trains	1.D. Total Transit	t Trains	1.E. Check if L		
(6 AM to 6 PM) 9		(6 PM 6	to 6 AM)		0			0		One Moveme	nt Per Day 🛛 🗌 ains per week?	
2. Year of Train Coun	t Data (YYYY)		. Speed of T	rain at Cross	- ing				now many tra		
0040	·	,	3	.A. Maximu	m Timetable	Speed	(mph) <u>6</u>	0 00	00			
2016 4. Type and Count of	Tracks		3	.B. Typical S	peed Range	Over C	rossing (n	nph) From <u>30</u>	to60			
		V-	_{ird} 0	Transit	+ 0	ام مر ا	ustry 0					
Main <u>1</u> 5. Train Detection (M	Siding <u>0</u> Iain Trai		iiu	i ransi	ι <u> </u>	_ ind	ustry_0_					
Constant Warr			Detection		ртс 🗆 рс		Other 🗆	None				
6. Is Track Signaled?	-				7.A. Event R	ecorde					e Health Monitoring	
I Yes I No □ Yes I No □ Yes I No									🗶 No			

U. S. DOT CROSSING INVENTORY FORM

A. Revision Date (MM/DD/YYYY) PAGE 2 D. Crossing Inventory Number (7 char.) 427247M														
Part III: Highway or Pathway Traffic Control Device Information														
1. Are there 2. Types of Passive Traffic Control Devices associated with the Crossing														
Signs or Signals? □ Yes ☑ No	2.A. Crossbuc Assemblies (c		(count)	DP Signs (R1-1)	2.C. (cour		;ns <i>(R1-2)</i>	□ W10-1 □ W10-3 □ W10-11						
	0		0											
2.E. Low Ground Cl (<i>W10-5</i>) □ Yes (count ⁰	Ū			Markings	i- F		Devices/	nnelization Medians		d:	2.H. EXEMP (<i>R15-3</i>)	T Sign	2.I. ENS S Displayed	
No No			op Lines Xing Sym	bols 🗆 No	iamic En ne	velope	🗆 One A	.pproach	🕱 Nor	☐ Median ☐ Yes ☐ Yes ■ None ■ No □ No				
2.J. Other MUTCD S	Signs	_	Yes 🗷 N	-			2.K. Priv Signs <i>(if</i>	ate Crossing	2.L.	LED Er	nhanced Signs	(List types	5)	
Specify Type Specify Type		Co	unt <u>0</u> unt <u>0</u> unt				□ Yes	-						
Specify Type					, .,				<u> </u>					
3. Types of Train A 3.A. Gate Arms	3.B. Gate Con						f each dev ged) Flashi				Mounted Flasl	ning Lights		3.E. Total Count of
(count)	S.B. Gale Con	iiguiatit	, , , , , , , , , , , , , , , , , , , ,	Structure			jeuj Flasili				nasts) 0	ling Lights		Flashing Light Pairs
. ,	🗆 2 Quad	🗆 Full	(Barrier)	Over Tra			🗆 Ir	candescent		ncande		LED		0.0
Roadway <u>0</u> Pedestrian	□ 3 Quad □ 4 Quad	Resista	ance dian Gate	s Not Over	Traffic L	ane_0_	Du	ED		Back Lig	hts Included	□ Side Include	-)
3.F. Installation Dat	te of Current			3.G. Wayside	Horn					3.H. H	lighway Traffi	c Signals C	Controlling	3.I. Bells
Active Warning Dev		,		□ Yes Ins	tallod or			/		Cross	ing	U	0	(count)
/	X	Not Rec	quired			1 (1011017 1		/		□ Ye	s 🗷 No			0
3.J. Non-Train Activ	0	Operated	l Signals	Uwatchman	Flood	lighting	🗆 None				Flashing Light S			
4.A. Does nearby H	wy 4.B. Hwy	Traffic S	Signal	4.C. Hwy Traf	fic Signal	Preemp	tion	5. Highway T	raffic F	Pre-Sigr	nals	6. Highw	ay Monitor	ring Devices
Intersection have	Intercon				🗆 Yes 🗷 f			No				heck all that apply)		
Traffic Signals?	Not II For T			□ Simultane	bus Storage Distan			nco *				Yes - Photo/Video Recording Yes – Vehicle Presence Detection		
🕱 Yes 🛛 No	□ For W			□ Advance							□ None			
				Р	art IV:	: Physi	cal Cha	racteristic	s					
1. Traffic Lanes Cro						adway/P	athway	3. Does T	rack Ru	ın Dow	n a Street?		•	inated? (Street
Number of Lanes 5. Crossing Surface I 1 Timber 🗌	0	Two Divi	o-way Tra ded Traffi	ffic c	Paved? א צו	Yes	□ No	[] Yes	X	No	nearest	rail) 🖪 Yes	x. 50 feet from □ No
5. Crossing Surface	e (on Main Track	, multip	le types a	llowed) Insta	llation Da	ate * (M	M/YYYY) _	/		Wi			Length * _	
8 Unconsolidate	ed 🗌 9 Com	o Aspr posite		ther (specify)	concrete	: 15	concrete	and Rubber		RUDDE		LdI		
6. Intersecting Roa	dway within 50	0 feet?					7. Smalle	est Crossing A	ngle			8. Is Co	mmercial P	ower Available? *
🛛 Yes 🗆 No	If Yes, Approxin	nate Dis	tance <i>(fee</i>	_{t)} 75			□ 0° – 2	9° □ 30°	- 59° 🖬 60° - 90° 📓 Yes □ No			□ No		
					t V: Pı	ublic H		Informat						
1. Highway System			2.	Functional Clas	sificatior	n of Road	at Crossi		3.		sing on State H	Highway	4. Hig	shway Speed Limit
□ (01) Inters	tate Highway Sy	/stem		(1) Interstate	(0) Rur		1) Urban	r Collector				MPH sted □ Statutory		
	Nat Hwy Syster			(2) Other Free	ways and						Referencing Sv	ystem (LRS		
	al AID, Not NHS			(3) Other Prin				r Collector	6	I RS Mi	lepost *			
(08) Non-F7. Annual Average			· · · · ·	(4) Minor Arte			(7) Local	d by School B				10	Emergence	y Services Route
Year 2001 AA	DT 268		03		%	□ Yes	🛛 🖾 No	Average Nu	mber p			_ 🗆 Y	/es 🗆 I	No
Subm	ission Infor	matio	n - This	information	is used	d for ac	lministro	itive purpo	ses ai	nd is r	ot availabl	e on the	public w	ebsite.
Submitted by				Organiz	ation						Phone		Dat	e
Public reporting bu	rden for this inf	ormatio	n collectio			ge 30 mi	nutes per	response, inc	luding	the tim		g instructi		
sources, gathering agency may not con displays a currently other aspect of this	and maintaining nduct or sponso valid OMB cont collection, inclu	g the dat r, and a trol num	a needed person is iber. The	and completin not required to valid OMB con	g and rev o, nor sha trol num	viewing t all a pers ber for i	he collecti on be subj nformatior	on of informa ect to a pena n collection is	ation. / Ity for 1 2130-0	Accordi failure 0017. S	ing to the Pape to comply with end comment	erwork Re h, a collect ts regardin	duction Act tion of info ng this burd	t of 1995, a federal rmation unless it en estimate or any
Washington, DC 20	530.													



Housing Community Development Department






Houston Airport Noise Contours

Docusign Envelope ID: 10C13B37-8068-4DAA-9622-A86ACA04641A U.S. Fish and Wildlife Service



National Wetlands Inventory

Wetlands - 1270 Hopper Rd.



May 6, 2024

Wetlands

Estuarine and Marine Wetland

Estuarine and Marine Deepwater

Freshwater Pond

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Lake Other Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.